LASER®

LTR Chain Checker

This chain wear indicator gauge should be used periodically to measure how much a chain has worn and stretched, ensuring it can then be replaced before it has caused any additional wear to the components that it runs on. A worn chain can be noisy, cause running and gear shifting issues and prematurely wear out sprockets and chain rings which can be costly to replace.



Additional Information

- Checks for chain wear & stretch.
- · Features link measurement gauge shown in mm increments & wear checking indicator showing percentage wear.
- Acts as a third hand to hold the two ends of the chain while links are fitted.
- · Also includes a thread thickness measurement scale.
- Manufactured from chrome molybdenum.

http://lasertools.co.uk/product/8160



Distributed by The Tool Connection Ltd. Kineton Road | Southam | Warwickshire | CV47 0DR I | +44 (0) 1926 815 000 F | +44 (0) 1926 815 888







LASER Kamasa Gunson Onnect Prec

18 Mar 2022